

# Troubleshooting and Maintaining Sloan CROWN II® & CROWN® Flushometers

## 1. PROBLEM: Valve does not function.

- CAUSE:** (a.) Control Stop or Main Valve is Closed.  
 (b.) Handle Assembly is worn.  
 (c.) Relief Valve is worn and sticking in UP position.

- SOLUTION:** (a.) Open Control Stop or Main Valve.  
 (b.) Install Sloan Handle Repair Kit (CR-1007 for CROWN II), (B-51-A for CROWN), or replace Handle.  
 (c.) Replace Piston.

## 2. PROBLEM: Insufficient volume of water to adequately siphon fixture.

- CAUSE:** (a.) Control Stop not open enough.  
 (b.) Urinal Piston Parts inside a Closet Valve.  
 (c.) Low Consumption Valve installed on a non-Low Consumption fixture.  
 (d.) Inadequate volume or pressure at supply.

- SOLUTION:** (a.) Adjust Control Stop for desired delivery of water.  
 (b.) Replace Piston Parts with proper Closet Piston.  
 (c.) Replace with proper Flushometer. Crown Flushometers are not available with flush volume higher than 1.6 gpf/6.0 Lpf.  
 (d.) Increase water pressure or supply (flow) to valve. Consult Factory for assistance.

## 3. PROBLEM: Length of flush too short (Short Flushing) or Valve closes off immediately.

- CAUSE:** (a.) Piston Assembly is not hand-tight.  
 (b.) Enlarged Bypass orifice from corrosion or damage.  
 (c.) Urinal Piston in Closet Flushometer.  
 (d.) Low Consumption Piston installed in non-Low Consumption fixture.  
 (e.) Handle Assembly worn.

- SOLUTION:** (a.) Screw the assembly hand-tight.  
 (b.) Install NEW Inside Parts Kit to correct problem and update Flushometer.  
 (c.) Replace Piston with proper Closet Piston.  
 (d.) Replace with proper Flushometer. Crown Flushometers are not available with flush volume higher than 1.6 gpf/6.0 Lpf.  
 (e.) Install Sloan Handle Repair Kit (CR-1007 for CROWN II) or (B-51-A for CROWN).

## 4. PROBLEM: Length of flush too long (Long Flushing) or fails to close off.

- CAUSE:** (a.) Piston is not seating properly or Bypass orifice is clogged because of foreign material, or Bypass orifice is clogged by an invisible gelatinous film from "over-treated" water.  
 (b.) Line pressure has dropped and is not sufficient to force Relief Valve to seat.  
 (c.) CR-125-A Main Seat is fouled with debris or is worn.

- SOLUTION:** (a.) Disassemble the working parts and wash thoroughly. **NOTE:** Size of the orifice in the Bypass is of utmost importance for the proper metering of water into the upper chamber of the valve. **DO NOT enlarge or damage this orifice.** Replace Piston if cleaning does not correct problem.  
 (b.) Shut off all control stops until pressure has been restored, then open them again.  
 (c.) Clean or replace CR-125-A Main Seat.

## 5. PROBLEM: Leaking at Handle Assembly.

- CAUSE:** (a.) The B-85 Seal may have deteriorated.  
 (b.) Handle Gasket has been omitted.  
 (c.) Valve Handle Bushing is worn.  
 (d.) Handle Trim Ring is reversed preventing gasket from sealing. (CROWN II only)

- SOLUTION:** (a.) Install new B-85 Seal. **NOTE:** The B-85 Seal will easily slide onto the Bushing if it is wet.  
 (b.) Install A-31 Handle Gasket or Sloan Handle Repair Kit (CR-1007 for CROWN II) or (B-51-A for CROWN).  
 (c.) Install Sloan Handle Repair Kit (CR-1007 for CROWN II) or (B-51-A for CROWN).  
 (d.) Flip Handle Trim Ring (CR-113) and reinstall Handle Assembly. (CROWN II only)

## CARE AND CLEANING INSTRUCTIONS

DO NOT use abrasive or chemical cleaners (including chlorine bleach) to clean Flushometers that may dull the luster and attack the chrome or special decorative finishes. Use ONLY soap and water, then wipe dry with clean cloth or towel.

While cleaning the bathroom tile, the Flushometer should be protected from any splattering of cleaner. Acids and cleaning fluids will discolor or remove chrome plating.

If further assistance is required, please contact the Sloan Valve Company Installation Engineering Dept. at 1-888-SLOAN-14 (1-888-756-2614).

Piston Identification Chart	Water Closet	Urinal	Urinal
	CR-135-A (0332024)	CR-137-A (0332025)	CR-138-A (0332026)
	1.6 gpf (6.0 Lpf)	1.0 gpf (3.8 Lpf)	0.5 gpf (1.9 Lpf)
<b>Cap Color</b>	Green	Yellow	Red
<b>Piston Color</b>	Clear	Clear	Clear
<b>Barrel</b>	Large Ribs	Small Ribs	Small Ribs
<b>Grooves</b>	1	1	3

**SLOAN VALVE COMPANY • 10500 SEYMOUR AVENUE • FRANKLIN PARK, IL 60131**

Phone: 1-800-9-VALVE-9 or 1-847-671-4300 • Fax: 1-800-447-8329 or 1-847-671-4380 • www.sloanvalve.com